Bid Notice Abstract

Request for Quotation (RFQ)

Reference Number 7429493

SOCIAL SECURITY SYSTEM - LUZON CENTRAL 2 **Procuring Entity**

Title PREVENTIVE MAINTENANCE (CHANGE OIL) OF EIGHT (8) SERVICE VEHICLE OF LUZON

CENTRAL 2 DIVISION

Area of Delivery Philippines

2021-002	Status	Pending
Implementing Rules and Regulations		
Negotiated Procurement - Small Value Procurement (Sec. 53.9)	Associated Components	1
Goods - General Support Services	Bid Supplements	0
General Repair and Maintenance Services		
PHP 38,934.00	Document Request List	0
7 Day/s		
	Date Published	26/01/2021
EDGIE SIMON DIMALANTA		
DIOSDADO MACAPAGAL GOVERNMENT CENTER MAIMPIS San Fernando City	Last Updated / Time	25/01/2021 16:26 PM
Philippines 2000 63-045-4555213 63-45-8613174 luzoncentral2@sss.gov.ph	Closing Date / Time	29/01/2021 08:00 AM
	Implementing Rules and Regulations Negotiated Procurement - Small Value Procurement (Sec. 53.9) Goods - General Support Services General Repair and Maintenance Services PHP 38,934.00 7 Day/s EDGIE SIMON DIMALANTA BAC SECRETARIAT DIOSDADO MACAPAGAL GOVERNMENT CENTER MAIMPIS San Fernando City Pampanga Philippines 2000 63-045-4555213 63-45-8613174	Implementing Rules and Regulations Negotiated Procurement - Small Value Procurement (Sec. 53.9) Goods - General Support Services General Repair and Maintenance Services PHP 38,934.00 Toay/s Document Request List Document Request List Date Published EDGIE SIMON DIMALANTA BAC SECRETARIAT DIOSDADO MACAPAGAL GOVERNMENT CENTER MAIMPIS San Fernando City Pampanga Philippines 2000 63-045-4555213 63-45-8613174 Closing Date / Time

Description

PREVENTIVE MAINTENANCE (CHANGE OIL) OF EIGHT (8) SERVICE VEHICLE OF LUZON CENTRAL 2 DIVISION

For 5,000 km mileage (Baliuag, Bocaue, Meycauayan, Pampanga, SJDM and OVP)

- 5,000 kms check-up
- Check Battery Charging
- · Engine Oil
- Oil Filter
- Drain Plug Gasket
- Other repairs/services required based on recommendations on pre-inspection report

For 10,000km mileage (Angeles and Malolos)

- 10,000 kms check-up Wheel Balance & Tire Rotate
- Check Battery
- Engine Flushing
 Car Care
- Engine Oil
- Oil Filter
- Drain Plug Gasket
- Injector CleanerBreak Cleaner
- · W. Weights (Approx)
- · Other repairs/services required based on recommendations on pre-inspection report

*Please see attached Canvass Form.

**Be guided accordingly on the second page of the Canvass Form.

For further inquiries, kindly call Ms. EDGIE S. DIMALANTA / Ms. CHELISSA ANN VIDAL, Division BAC Secretariat at telephone numbers (045) 455-5359|5360|5213 or email address luzoncentral2@sss.gov.ph.

Thank you.

Created by EDGIE SIMON DIMALANTA

Date Created 25/01/2021

The PhilGEPS team is not responsible for any typographical errors or misinformation presented in the system. PhilGEPS only displays information provided for by its clients, and any queries regarding the postings should be directed to the contact person/s of the concerned party.